

surveyed 1858 - Wm. Hutton.

No 1. — a stone — original trees standing.

No 2 — a stone, N.S. line W. $\frac{1}{4}$ ~~the~~ N. corner

White Oak - N. $60\frac{1}{2}^{\circ}$ W - $42\frac{1}{4}$ links

Poplar (7") - S $4\frac{1}{2}^{\circ}$ E - 24 links.

No 3 — stone — 8" Hickory - N 4° W - 5 links

a stone S. 25 links.

No 4 — a stone — 24" Poplar - S 70° W - 50 links.

No 5 — a stone — 12" Hickory - S 47° W - $34\frac{1}{2}$ links

5" Dog Wood - S 44° E - 18 links.

No 6 — stone — 2" B. Walnut - S $60\frac{1}{4}^{\circ}$ E - $36\frac{1}{2}$ links

8" Mulberry - N 43° W - $40\frac{1}{2}$ links.

No 7 — stone — 5" Black Walnut - N 86° E - $36\frac{1}{3}$ links

Hickory sprout - S $52\frac{1}{2}^{\circ}$ W - 5 links.

No 8 — stone — 6" Sycamore - S 10° E - $9\frac{1}{2}$ links

20" White Oak N $11\frac{1}{2}^{\circ}$ W - 88 links

No 9 — stone — Sugar 19" - S $53\frac{1}{2}^{\circ}$ E - $10\frac{1}{2}$ links

Beech 24" - N $25\frac{1}{2}^{\circ}$ W - $21\frac{3}{4}$ links.

No 14 — S. stone — 9" x 17" - 10 chs. E of Cor # 8

No 15 — Nig. head — 9" x 12" - 10.0 $9\frac{1}{4}$ N. of ~~the~~ # 7

No 16 — Flint 10 x 12 - 10.00 ch. W. of # 15.

No 6 Reset — Iron Bolt $3\frac{1}{4}$ " x 22" - Beech 20" - N $67\frac{1}{2}^{\circ}$ E - 35.5'

B. Walnut 6" - S. 37° W. - 55.4'