


Surveyed by John J. Peyton, County Surveyor and corners from 1 to 8 established March the 24th 1853.
The Bearings taken at a variation of 6°



- Corner No. 1 1/4 mile N of S.E. corner of Section 30 Sand Stone marked 1/8 S.
B. Oak 24 S 70° 30' E 47 L.
Do. 20 S 13° W 57 "
- " " " " " " " " " " " "
- " No. 2 1/4 E of S.W. corner (nearly) Sand Stone marked 1/8 S.
J Oak 6 S 5° W 56
Do. 3 S 43° E 65
- " " " " " " " " " " " "
- " No. 3 S.W. corner 152 L South the corner of sections 35 and 36 on the Rangeline
" " Sand Stone marked S30 and S31. (No timber near)
- " No. 4 1/2 mile post on N side Sand Stone marked 1/4 S.
W. Oak 24 N 27° 35' E 76.
A Hickory 24 S 65° W 53.
- " " " " " " " " " " " "
- " No. 5 In center between No 4 and 6 Sand Stone marked 1/8 S.
Birch 10 N 40° W 11 L.
W Walnut 11 S 59° E 42 "
- " " " " " " " " " " " "
- " No. 6 Center of Section Sand Stone marked 1/4 S
Sugar 18 S 20° W 18
Poplar 12 N 54° 35' E 50.
- " " " " " " " " " " " "
- " No. 7 Dr. corner E of center Sand Stone marked 1/8 S
Cherry 9 S 29° W 28 L.
Sassafras 18 N 35° E 34 L
- " " " " " " " " " " " "
- " No. 8 On N Section line 1/4 E. of N.W. corner Sand Stone marked 1/8 S.
W. Oak 16 S 41° E 111 L.
Do 36 N 53° E 109 "