

Corner 10 a Sand Stone m 31. 11. 7

" " No timber near

" " 80 Rods & 8 lks. It of N.E. cor.

Corner 11 a Sand Stone m 74 31

" " Witness a Jack Oak 5 S 28 1/2 E 45 lks.

" " a do. 10 S 12 E 64 "

Corner 12 a Sand Stone m 74. 31

Witness a Jack Oak 3 N 49 W 8 "

a do. 3 S 55 W 29 "

Surveyed and Recorded by P. J. Suther.

Surveyor Clay County Indiana.

Further Surveyed by Thomas B. Robertson surveyor of Clay county Indiana September 17th 1894 by request of L. C. Recla and consent of interested parties and corners 13 and 14 set

Cor. No 13 A Sand Stone marked 8 at middle of south line

No 14 Is corner No 8 Reset is exactly 59.92 chains East from S.W. ce.

Further surveyed by Fred C. Wilson Dep. S. C. C. Sept 4, 1907 after ten days notice had been given all interested parties, the following corners were set:

Cor. 12 - (Reset) S & 20" m x - 13 13 1/2 Ft. South of N.E. Sec. cor.

" 15 - S & 16" m x - 13 12 1/10 Ft. South of Cor 4